


# **Engineered Plastics Versions – Standard Size**

- Femperatures to 280°F (139°C)
- Pressures to 150 psi (10.3 bar)
- Up to 19 feet (5.8 meters) of continuous visual indication

The 2" Schedule 80 pipe design is ideal for use on chemical storage tanks, or with almost any liquid where temperature and pressure requirements are moderate. All SureSite Indicators feature the same patented flag and guide assemblies used on our alloy versions, so you can be assured of excellent visibility and long-life reliability.

### 1. Mounting Configuration Types

To choose the best configuration for your application, focus on the process connections (connections where the liquid typically enters/leaves the SureSite).



\* Dimensional data varies due to connections, material and specific gravity.

Note: Additional materials, floats, connections and manufacturing techniques are available to extend lengths and operational capabilities. Please contact GEMS Sensors if the parameters above do not meet your requirements.

### 2. Material


Select desired material from those tabulated below. Mark the Code Number on your Orderlt! Check List. The pressure/temperature performance parameters are specified in the charts at right. Consult the factory with pressure/temperature requirements that fall outside the parameters shown here.

Best economy and delivery).

Materials	Onda
Housing & Float	– Code
PVC	1
Clear PVC Housing/ PVC Float	1A*
* 0"Cohodula 10 pipa	•

\* 2" Schedule 40 pipe

### Pressure/Temperature Performance






ORDERIT



D-10

## SURESITE<sup>®</sup> LEVEL INDICATORS



B6

2

Ш

### Connection Code Descriptions

Please provide all connections when completing the Orderlt! Product Check List. **Note**: Before selecting your connections, consider incorporating your vent and drain requirements.

B

#### T & B (Top and Bottom)

- T/B 1. Welded cap
- T/B 2. Threaded cap (PVC only)
- T/B 3. Fixed flange/blind mating flange
- T/B 4. Welded coupling/FNPT
- T/B 5. Welded coupling/MNPT
- T/B 6. Threaded union/MNPT
- T/B 7. Fixed flange/mating flange MNPT
- T/B 9. Fixed flange/mating flange/FNPT
- T/B 10. Welded coupling flange
- T/B 11. Threaded union flange

# Accessories – Pages D-17 to D-19

Make more of your SureSite<sup>®</sup> Indicator with the productivity-enhancing accessories found at the end of this section.

- Indicating Scales
- Add graduations to your flag indication.
- Switch Modules

Control pumps, valves, alarms, etc. Mount externally on housing for infinite positioning.

• Continuous Output Transmitters Signal conditioned for compatibility with most electronic instruments.

#### Sa & Sb (Sides)

لمل

- S1 Blind-No Connection
- S2 MNPT nipple
- S3 FNPT coupling
- S4 ANSI flange

FAXITE 860-747-424 Photocopy This Use one form for each type you are select	This is a Reque C Order Quantity Needed Date Required Shipping Method: Partials Accepted:	P.O.#	— Cor — Str — Cit <u>y</u> — Pho	mpany eet y one ( )	State	_ Zip	
SureSite Indic Process Conditions This information is essential to t SureSite® Visual Level Indicators	<mark>S</mark> the accurate and p	proper operation of y	/our	stic V	/ersions -	– Standard	Size
. Pressure: Operating				-		ing Condition:	
<ol> <li>Temperature: Operating</li> <li>Liquid Media:</li> </ol>					ity:	SSU ndoors □ Outdoors	
. Mounting Configuration	n Types:						
□ Type AP □ Type BP 3. Connection Codes – Co ▼ Connection Code Numb	Type CP	nection code lines		Code 1	nge size where appr	] Code 2 ropriate.	
□ Type AP □ Type BP 3. Connection Codes – Co	Type CP	nection code lines		Code 1	I □ Code 1A □	] Code 2 ropriate.	
□ Type AP □ Type BP 3. Connection Codes – Co ▼ Connection Code Numb Top T	Type CP	nection code lines	nbers and th	Code 1	Code 1A	] Code 2 opriate. <b>D-11.</b>	
□ Type AP □ Type BP 3. Connection Codes – Co ▼ Connection Code Numb Top T	Type CP omplete all 4 con per Goes Here. Cor NPT	nection code lines	nbers and th	□ Code 1 NPT or Flai neir descrij	Code 1A	] Code 2 ropriate.	
□ Type AP □ Type BP 3. Connection Codes – Co ▼ Connection Code Numb Top T Side Sa	Type CP per Goes Here. Cor NPT 1/2" 11" 0 Other	2"	nbers and th	□ Code 1 NPT or Flai neir descrij	I Code 1A nge size where appr ptions are on Page I Flange I 50# (FF) Other Flange Flange I 50# (FF)	] Code 2 opriate. <b>D-11.</b>	
□ Type AP □ Type BP 3. Connection Codes – Co	Type CP      Type CP      omplete all 4 con     per Goes Here. Cor          1/2" 11"          1/2" 11"          NPT          1/2" 11"          1/2" 11"	2"	nbers and th	Code 1 NPT or Flat Neir descrip	I Code 1A nge size where appr ptions are on Page I Flange I 50# (FF) Other Flange Flange I 50# (FF)	1 Code 2 ropriate. D-11.	
<ul> <li>Type AP □ Type BP</li> <li>Connection Codes – Co</li> <li>Connection Code Numb</li> <li>Top T</li> <li>Side Sa</li> <li>Side Sb</li> </ul>	Type CP     Type CP     Type CP     Der Goes Here. Cor     NPT     1/2" 1"     Other     NPT     1/2" 1"     Other	2" 1/2" 2" 1/2" 2" 1/2" 2" 1/2"	nbers and th	Code 1 NPT or Flat Neir descrip		1 Code 2 ropriate. D-11.	
<ul> <li>Type AP □ Type BP</li> <li>Connection Codes – Co</li> <li>Connection Code Numb</li> <li>Top T</li> <li>Side Sa</li> <li>Side Sb</li> </ul>	Type CP Type	2" □ 1/2" 2" □ 1/2" 2" □ 1/2" 2" □ 1/2" 2" □ 1/2" 2" □ 1/2"	nbers and th	Code 1 NPT or Flan neir descrip 2" 2"	I Code 1A nge size where appr ptions are on Page I Flange I 150# (FF) Other Flange Flange Flange Flange I 50# (FF) Other Flange I 150# (FF) I 00 (FF)	1 Code 2 ropriate. D-11.	
☐ Type AP ☐ Type BP 3. Connection Codes – Co	Type CP	nection code lines         nnection Code Nun         2"       1/2"         2"       1/2"         2"       0 ther         2"       0 ther         2"       0 ther         2"       0 ther         2"       1/2"         0 ther          2"       0 ther         2"       1/2"         2"       1/2"         2"       1/2"	nbers and th	Code 1 NPT or Flan neir descrip 2" 2"	I          Code 1A          Inge size where appropriations are on Page I         Flange         I       150# (FF)         Other	1 Code 2 ropriate. D-11.	
☐ Type AP ☐ Type BP 3. Connection Codes – Co	□ Type CP  Der Goes Here. Cor  Der Goes Here. Cor  1/2" □ 1" □  Other  1/2" □ 1" □  1/2" □ 1" □  1/2" □ 1" □  1/2" □ 1" □  NPT  1/2" □ 1" □  NPT  1/2" □ 1" □  NPT  1/2" □ 1" □  Ation - L:	nection code lines         nnection Code Nun         2"       1/2"         2"       1/2"         2"       0 ther         2"       0 ther         2"       0 ther         2"       1/2"         2"       0 ther         2"       0 ther	nbers and th	Code 1 NPT or Flan Neir descrip 2" 2" 2" 2" 2"	I <ul> <li>Code 1A</li> <li>Inge size where appropriations are on Page I</li> <li>Flange</li> <li>I 150# (FF)</li> <li>Other</li> <li>Other</li> <li>Flange</li> <li>I 150# (FF)</li> <li>Other</li> <li>Other</li></ul>	1 Code 2 ropriate. D-11.	  C.)

Accessories	(rages D-11 to D	-19)	
□ Standard – 300°F	tinuous Electrical Indicatior (149°C) ditioners Accessories:	):	<ul> <li>4. Switch Modules (Single Point): Quantity (only if required)         <ul> <li>a. □ SPST □ SPDT □ DPDT 120 VAC □ DPDT 24 VDC</li> <li>b. □ Standard - 300°F (149°C) □ High Temperature</li> </ul> </li> </ul>
<ul> <li>Terminal Strip</li> <li>0–12 VDC Output</li> <li><b>3. Power Supply:</b> (Optional)</li> </ul>			5. Indicating Scales:
Please contact Gems f ered on this form. <b>800</b> Quote: \$	or any configuration or spec - <b>378-1600</b> Date Quoted:	cial requirements not cov-	Gem Sensors&Cont



ORDERITI